
DTC	B1242	Wireless Door Lock Tuner Circuit Malfunction	
RECORDINA			

DESCRIPTION


When a RDA signal is not input to the door control receiver within 1 second after the multiplex network body ECU outputs a PRG signal, this DTC is set.


DTC No.	DTC Detection Condition	Suspected Area
B1242	Within 1 second after PRG signal is output from multiplex network body ECU during self-diagnostic mode, corresponding RDA signal is not input	Wire harnessDoor control receiverMultiplex network body ECU

WIRING DIAGRAM



1 CHECK HARNESS AND CONNECTOR (MULTIPLEX NETWORK BODY ECU - DOOR CONTROL RECEIVER)





- (a) Reconnect the multiplex network body ECU connector.
- (b) Replace the door control receiver.
- (c) Perform the REGISTRATION procedures (See page DL-66).

HINT:

If there is a new door control receiver or one functioning normally available, connect it and check if the wireless door lock function is normal or the DTC is output. If the alternative receiver functions normally, replace the original door control receiver.

NEXT

5

RECHECK DTC

- (a) Clear the DTC (See page DL-78).
- (b) Check if the same DTC is detected. HINT:

Reinstall the sensors, connector, etc. and restore the vehicle to its previous condition before rechecking for DTCs.

Result

Condition	Proceed To
DTC (B1242) is output	A
DTC (B1242) is not output	В



A

REPLACE MULTIPLEX NETWORK BODY ECU

Dľ