DTC B2797 Communication Malfunction No. 1

DESCRIPTION


This DTC is output when an error occurs in normal communication.

HINT:


Some noise found in the communication line.

DTC No.	DTC Detection Condition	Trouble Area
B2797	Keys are positioned too close to each other, or noise occurred in communication line.	 Key Transponder key amplifier Wire harness Transponder key ECU assembly

WIRING DIAGRAM



1 CHECK KEY



 (a) Check whether the ignition key being used is near other ignition keys, as shown in the illustration. Also, check whether the key ring is in contact with the key grip.
 Result

Result	Proceed to
Key is near other keys and/or key ring is in contact with key grip.	Α
Key is not near other keys and / or key ring is not in contact with key grip.	В

B Go to step 3



2 CHECK FOR DTC

- (a) Delete the DTC (See page El-15).
- (b) Insert the key into the ignition key cylinder.



(c) Check that no code is output.

OK:

No DTC is output.

OK NO PROBLEM




OK


3 CHECK TRANSPONDER KEY AMPLIFIER

T9 Transponder Key ECU Assembly

Wire Harness Side Connector Rear View:



T8 Transponder Key Amplifier



(a) Using an oscilloscope or the intelligent tester, check the waveform between the terminals of the T8 amplifier and T9 ECU connector.

Check that no noise is included in the waveform (an example of noise is shown on the left).

(b) Check that no noise is included in the waveform (an example of noise is shown on the left).

Result

Tester Connection	Specified Condition
T8-4 (CODE) - T9-10 (CODE)	No noise is present
18-4 (CODE) - 19-10 (CODE)	No noise is present

Tool Setting	2 V/DIV., 20 ms/DIV.
Condition	Key inserted into ignition key cylinder.


NG

B111615E04

FIND CAUSE OF NOISE AND REMOVE NOISE



4 CHECK HARNESS AND CONNECTOR (TRANSPONDER KEY ECU - TRANSPONDER KEY AMPLIFIER)



- (a) Disconnect the T9 ECU and T8 amplifier connectors.
- (b) Measure the resistance according to the value(s) in the table below.

Resistance

Tester Connection	Specified Condition
T9-10 (CODE) - T8-4 (CODE)	Below 1 Ω

NG

REPAIR OR REPLACE HARNESS OR CONNECTOR



OK

5 CHECK OPERATION OF TRANSPONDER KEY AMPLIFIER

(a) After replacing the transponder key amplifier with a normally functioning transponder key amplifier, check that the engine starts.

OK:

The engine starts

NG

REPLACE TRANSPONDER KEY ECU ASSEMBLY

OK

END (TRANSPONDER KEY AMPLIFIER DEFECTIVE)