

SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN			IN	No. : MSB-97E52-001		
				Date : 1997-04-30	<model></model>	<m y=""></m>
Subject:	ibject: ADDITION OF SRS AIR BAG M PROCEDURE			G MAINTENANCE	ALL MODELS	91-10
Group:	ip: INTERIOR I		Dra	aftno: 96-AL-022		
INFORMATION		OVERSEAS SERVICE DEPT		R. Usami R. Usami - MANAGER QUALITY INFORMATION ANALYSIS		

1. Description:

In the SRS air bag troubleshooting, items of cause of trouble in the inspection procedure for each diagnostic trouble code, have been added.

2. Applicable Vehicles:

- '91~'10 SIGMA
- '92~'10 3000GT
- '91~'10 COLT/LANCER
- '93~'10 GALANT
- '92~'10 SPACE RUNNER/SPACE WAGON
- '95~'10 L400
- '91~'10 PAJERO/MONTERO
- '97~'10 L200


3. Applicable Manuals:


Manual	Pub. No.	Language	Page(s)
SIGMA Workshop Manual chassis	PWGE9004-G	(English)	52B-14
	PWGS9005-F	(Spanish)	
	PWGF9006-F	(French)	
	PWGG9007-F	(German)	
	PWGD9008-F	(Dutch)	
	PWGW900-F	(Swedish)	
3000GT Workshop Manual chassis	PWUE9119-D	(English)	52B-12
'97 3000GT Workshop Manual chassis	PWUE9119-F	(English)	52B-6
Supplement			
COLT/LANCER Workshop Manual chassis	PWME9117-D	(English)	52B-12
	PWMS9118-D	(Spanish)	
	PWMF9119-D	(French)	
	PWMG9120-D	(German)	
	PWMD9121-D	(Dutch)	
	PWMW9122-D	(Swedish)	

Manual	Pub. No.	Language	Page(s)
95'COLT/LANCER Workshop Manual	PWME9117-E	(English)	52B-7
chassis Supplement	PWMS9118-E	(Spanish)	
	PWMF9119-E	(French)	
	PWMG9120-E	(Ġerman)	
	PWMD9121-E	(Dutch)	
	PWMW9122-E	(Swedish)	
'97 COLT/LANCER Workshop Manual	PWME9117-F	(English)	52B-5
chassis Supplement	PWMS9118-F	(Spanish)	
	PWMF9119-F	(French)	
	PWMG9120-F	(German)	
	PWMD9121-F	(Dutch)	
	PWMW9122-F	(Swedish)	
'96 COLT/LANCER Workshop Manual	PWME9511	(English)	52B-8
chassis	PWMS9512	(Spanish)	
	PWMF9513	(French)	
	PWMG9514	(German)	
	PWMD9515	(Dutch)	
	PWMW9516	(Swedish)	
GALANT Workshop Manual chassis	PWDE9211-B	(English)	52B-13
'	PWDS9212-B	(Spanish)	
	PWDF9213-B	(French)	
	PWDG9214-B	(German)	52B-11
	PWDD9215-B	(Dutch)	52B-13
	PWDW9216-B	(Swedish)	
'96 GALANT Workshop Manual	PWDE9211-D	(English)	52B-7
chassis Supplement	PWDS9212-D	(Spanish)	
	PWDF9213-D	(French)	
	PWDG9214-D	(German)	
	PWDD9215-D	(Dutch)	
	PWDW9216-D	(Swedish)	
SPACE RUNNER/SPACE WAGON	PWDE9104-D	(English)	52B-9
Workshop Manual chassis	PWDS9105-D	(Spanish)	
·	PWDF9106-D	(French)	
	PWDG9107-D	(German)	
	PWDD9108-D	(Dutch)	
	PWDW9109-D	(Swedish)	
'95 SPACE RUNNER/SPACE WAGON	PWDE9104-E	(English)	52B-8
Workshop Manual chassis Supplement	PWDS9105-E	(Spanish)	
, , , , , , , , , , , , , , , , , , , ,	PWDF9106-E	(French)	
	PWDG9107-E	(German)	
	PWDD9108-E	(Dutch)	
	PWDW9109-E	(Swedish)	

52B-12 SUPPLEMENTAL RESTRAINT SYSTEM (SRS) - Troubleshooting

Code No. 21, 22	Air bag module (squib) system	Probable cause of trouble		
(Explanation)	These codes are output when the resistance value between the air bag module (squib) terminals in the SDU is out of the normal range. The probable causes of trouble associated with the respective code Nos. Are as follows.	 Defective clock spring Open circuit in clock spring due to inappropriate neutral position Defective harness, connector Defective air bag module (squib) Defective SDU 		
Code No.	Probable cause of trouble			
21	Air bag module (squib) or harness short-circuited Clock spring short-circuited			
22	 Air bag module (squib) or harness open-circuited Clock spring open-circuited Disconnected connector in the driver's side air bag module (squib) 			
	 Open-circuit in clock spring due to inappropriate neutral position Connector in loose contact 	- \Added2		





Caution


- 1. After the ignition switch has been placed at the LOCK position and the negative (-) terminal of the battery has been disconnected, wait for more than 60 seconds before starting work. Wind a tape around the disconnected (-) terminal for insulation. (Refer to P.52B-4, No. 5)
- Do not attempt to measure the air bag module (squib)
 circuit resistance. Use of a tester in measuring the circuit
 resistance will supply current to the squib, or erroneous
 deployment due to static electricity could cause serious
 injury.
- To unlock the SDU connector, place a flat-tipped screwdriver against the lock spring at the lock lever notch and push the spring toward the unit. In this case, do not force the lock lever up.


INSPECTION PROCEDURE FOR DIAGNOSIS CODES

Code No. 21,22 Air bag module (Driver's side squib) system	Probable cause of trouble
(Explanation)	Defective clock spring
These codes are output when the resistance value between the air bag module (squib)	Open-circuit in clock spring
terminals in the SDU is out of the normal range.	due to inappropriate neutral
The probable causes of trouble associated with the respective codes Nos. are as fol-	position
lows. <refer 1.="" chart="" the="" to=""></refer>	Defective harness,
	connector
<added></added>	Defective air bag module
Tradous	(driver's side squib)
	Defective SDU

CHART 1

Code No.	Probable cause of trouble		
21	Air bag module (driver's side squib) or harness short-circuited		
	Clock spring short-circuited		
22	Air bag module (driver's side squib) or harness open-circuited		
	Clock spring open-circuited		
	Disconnected connector in the driver's side air bag module (squib) Added> Added>		
	Open-circuit in clock spring due to inappropriate neutral position		
	Connector in loose contact		





Caution

- 1. After the ignition switch has been placed at the LOCK position and the negative (-) terminal of the battery has been disconnected, wait for more than 60 seconds before starting work. Wind a tape around the disconnected (-) terminal for insulation. (Refer to P.52B-4, No. 5)
- 2. Do not attempt to measure the air bag module (squib) circuit resistance. Use of a tester in measuring the circuit resistance will supply current to the squib, or erroneous deployment due to static electricity could cause serious injury
- To unlock the SDU connector, place a flat-tipped screwdriver against the lock spring at the lock lever notch and push the spring toward the unit. In this case, do not force the lock lever up.