

SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN				No. : MSB-97E52-50		
				Date : 1997-11-24	<model></model>	<m y=""></m>
Subject:		CORRECTION TO CAUTIO MODULE AND CLOCK SPR			(EC,EXP)L400 (PA0V) (EC,EXP)PAJERO (V10,V20,V30,V40) (EC,EXP)SIGMA	96-10 92-10 91-10 96-10 96-10
Group:	SUPPLEMENTAL RESTRAIN		Dra	aftno: 97-AL-019	(F10,F20) (EC,EXP)COLT (CJ0A) (EC,EXP)LANCER	
CORRECTION		OVERSEAS SERVICE DEPT	,	R. Usami R. Usami - MANAGER QUALITY INFORMATION ANALYSIS	(CK0A) (EC,EXP)GALANT (EA0)	

1. Description:

This Service Bulletin informs you that caution on air bag module and clock spring has been corrected.


2. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
'97 GALANT Workshop Manual chassis	PWDE9611	(English)	52B-32
	PWDS9612	(Spanish)	
	PWDF9613	(French)	
	PWDG9614	(German)	
	PWDD9615	(Dutch)	
	PWDW9616	(Swedish)	
'96 COLT/LANCER Workshop Manual	PWME9511	(English)	52B-25
chassis	PWMS9512	(Spanish)	
	PWMF9513	(French)	
	PWMG9514	(German)	
	PWMD9515	(Dutch)	
	PWMW9516	(Swedish)	
'95 L400 Workshop Manual chassis	PWWE9410	(English)	52B-37
	PWWS9411	(Spanish)	
	PWWF9412	(French)	
	PWWG9413	(German)	
	PWWD9414	(Dutch)	
	PWWW9415	(Swedish)	

INSTALLATION SERVICE POINTS **▶**A SRS-ECU INSTALLATION

Caution

The SRS may not activat if SRS-ECU is not installed properly, which could result in serious injury or death to the vehicle's driver or front passenger.



▶ B ◆ POST-INSTALLATION INSPECTION

- 1. Reconnect the negative battery terminal.
- 2. Turn the ignition key to the "ON" position.
- 3. Does the "SRS" warning lamp illuminate for about 7 seconds, and then remain extinguished for at least 5 seconds after turning OFF?
- 4. If yes, SRS system is functioning properly. If no, consult page 52B-6

INSPECTION

52400220062

- Check the SRS-ECU and brackets for dents, cracks or deformation.
- Check connector for damage, and terminals for deformation.

Caution

If a dent, crack, deformation or rust is discovered, replace the SRS-ECU with a new one.

NOTE

For checking of the SRS-ECU other than described above, refer to the section concerning troubleshooting. (Refer to P.52B-6.)

AIR BAG MODULES AND CLOCK SPRING

52400240112

Caution

- 1. 1. Disconnect the battery (-) terminal and wait for 60 seconds or more before starting work. Furthermore. disconnected battery terminal should be covered with tape to insulate it. (Refer to
- 2. Never attempt to disassemble or repair the air bag modules or clock spring. If faulty, replace it.
- 3. Do not drop the air bag modules or clock spring or allow contact with water, grease or oil.
 - Replace it if a dent, crack deformation or rust is detected.

- 4. The air bag modules should be stored on a flat surface and placed so that the air bag deployment surfaces are facing upward.
 - Do not place anything on top of it.
- 5. Do not expose the air bag modules to temperatures over 93°C.
- 6. After deployment of an air bag, replace the clock spring with a new one.
- 7. Wear gloves and safety glasses when handling air bags that have already deployed.
- 8. An undeployed air bag module should only be disposed of in accordance with the procedures (Refer to P.52B-34.)

<Correct> After deployment of an air bag, replace the air bag modules. Check the clock spring, and if faulty, replace it with a new part.