

## SERVICE BULLETIN

### APPLICABILITY

ALL LEGACY 2.2 LITER ENGINES,  
PRODUCED BEFORE ENGINE #345344 (TURBO)  
AND 339610 (NATURALLY ASPIRATED)

### DATE

09-17-


### SUBJECT:

ENGINE OIL SEEPAGE AT CYLINDER HEAD OR  
ACCESSORY MOUNTING BOLTS

Should you encounter engine oil seepage from the open bolt hole at the top of the right hand cylinder head near the rear, the actual cause of this leak may be porosity of the cylinder block and not at the bolt hole where the oil is seeping. (See Figure 1.)


To repair this condition:

1. Remove air intake duct (non-turbo). Remove air intake resonator chamber (turbo).
2. Remove air cleaner housing assembly from engine compartment.
3. Remove the top rear cylinder head bolt from the right cylinder head.
4. Carefully clean all oil from the bolt threads and from the cylinder block threads using a quality non-petroleum based cleaner, i.e. a spray brake cleaner.
5. Apply THREE BOND 1215 sealer (P/N 004403007) to the cylinder head bolt threads.  
DO NOT APPLY EXCESSIVE SEALER TO THREADS.  
DO NOT APPLY SEALER TO THREADED HOLES IN CYLINDER BLOCK.  
DO NOT APPLY OIL TO THE BOLT THREADS.
6. Reinstall the affected bolt and retorque to the following REVISED specification.  
Tighten bolt to 20 N.m (2.0 Kg-m, 14 ft-lbs).  
Tighten bolt an additional 80-90 Degrees.  
DO NOT TIGHTEN BOLT MORE THAN 90 DEGREES.



Legacy 2.2 Liter Engine  
RH Cylinder Head  
Figure 1

Legacy 2.2 Liter Engine  
Accessory Mounting Bolts  
Figure 2



Clean Affected  
Accessory Mounting  
Bolt Holes

In addition, should you encounter engine oil seepage from any accessory mounting bolts, the following procedures must be performed to ensure a permanent effective repair.

1. Remove the affected bolt.
2. Thoroughly clean all oil from the bolt and the cylinder block threads with a quality non-petroleum based cleaner, i.e. a spray brake cleaner. (See Figure 2.)
3. Apply THREE BOND 1215 sealer P/N 004403007 to the bolt threads.  
DO NOT APPLY EXCESSIVE SEALER TO THREADS.  
DO NOT APPLY SEALER TO THREADED HOLES IN CYLINDER BLOCK.  
DO NOT APPLY OIL TO BOLT THREADS.

Reinstall the affected bolt and retorque to the proper specification.

#### Flat Rate Information

ITEM DESCRIPTION/ FAILURE CODE	OPERATION NUMBER	LABOR DESCRIPTIONS	LEGACY
Crankcase Head Bolt Hole AEU-34	A124-311	Crankcase Head Bolt Hole - RE-SEAL	0.7
Accessory Mounting Bolt Hole ZAA-34	A165-711	Power Steering Pump Mounting Bolt RE-SEAL	0.7
	A181-201	Alternator Mounting Bolt - RE-SEAL	0.4
	A101-401	A/C Compressor Mounting Bolt RE-SEAL (includes refrigerant RECOVERY, EVACUATE, AND RE-CHARGE A/C System)	1.6

#### CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.