

SYMBOLS

The following symbols are used in the welding Diagrams in Section RE of this manual to indicate cutting areas and the types of weld required.






















SYMBOLS	MEANING	ILLUSTRATION
	<p>SAW CUT OR ROUGH CUT</p>	
	<p>REMOVE BRAZE</p>	
 	<p>WELD POINTS</p> <p>SPOT WELD OR MIG PLUG WELD</p> <p>(See page IN-5)</p>	
	<p>CONTINUOUS MIG WELD (BUTT WELD OR TACK WELD)</p>	
	<p>BRAZE</p>	
	<p>BODY SEALER</p>	

Illustration of Weld Point Symbols

EXAMPLE:



SYMBOL	MEANING	ILLUSTRATION	SYMBOL	MEANING	ILLUSTRATION
<p>○ M I</p>	<p>Remove Weld Points</p>		<p>○ M I</p>	<p>Spot Weld</p>	
<p>○</p>	<p>(Outside)</p>		<p>○ M I</p>	<p>Mig Plug Weld</p>	
<p>M</p>	<p>(Middle)</p>		<p>+</p>	<p>Spot MIG Weld</p>	
<p>I</p>	<p>(Inside)</p>		<p><i>HINT: Panel position symbols are as seen from the working posture.</i></p>		