POWER ASSISTED SYSTEM (POWER STEERING)

10.General Diagnostic Table

A: INSPECTION

Trouble	Possible cause	Corrective action	
 Steering effort is heavy in all ranges. Steering effort is heavy at stand still. Steering wheel vibrates when turning. 	 Pulley belt Unequal length of pulley belts Contact with oil or grease Looseness or damage of the pulley belt Poor uniformity of the pulley belt cross section Pulley belt is touching the pulley bottom. Poor revolution of pulleys (except oil pump pulley) Poor revolution of oil pump pulley 	Adjust or replace.	
	 2. Tire and wheel Improper tires out of specifications Improper wheels out of specification Tires not properly inflated*1 	Replace or reinflate.	
	 3. Fluid Low fluid level Air entry in fluid Dust entry in fluid Fluid deterioration Inadequate warm-up of fluid *2 	Refill, bleed air, replace or instruct customer.	
	 4. Idle speed Low idle speed Excessive drop of idle speed at start or when turning the steering wheel *3 	Adjust or instruct customer.	
	5. Measure the hydraulic pressure. <ref. hydrau-<br="" ps-45,="" to="">LIC PRESSURE, INSPECTION, Oil Pump.></ref.>	Replace the problem parts.	
	6. Measure the steering wheel effort. <ref. mea-<br="" ps-53,="" to="">SUREMENT OF STEERING EFFORT, INSPECTION, General Diagnostic Table.></ref.>	Adjust or replace.	
 Vehicle leads to one side or the other Returning force of steering wheel to center is poor. Steering wheel vibrates when turning. 	 Fluid line Folded hose Flattened pipe 	Correct or replace.	
	 2. Tire and wheel Flat tire Mixed use of different tires Mixed use of different wheels Uneven tire wear Unequal tread remaining Unequal pressure of tire 	Correct or replace.	
	 3. Front alignment Improper or unequal caster Improper or unequal toe-in Loose suspension connections 	Adjust or retighten.	
	4. OthersDamaged joint assemblyUnbalanced heightUnbalanced weight	Replace, adjust or instruct cus- tomer.	
	5. Measure the steering wheel effort. <ref. mea-<br="" ps-53,="" to="">SUREMENT OF STEERING EFFORT, INSPECTION, General Diagnostic Table.></ref.>	Adjust or replace.	

*1 If the tires or wheels are wider than standard, the load to power steering system is increased. Accordingly, in a condition where the fluid has not yet warmed up, the relief valve may work before reaching the maximum turning angle. In this case, steering effort may be heavy. When the measured hydraulic pressure is normal, there is no problem.

*2 In cold weather, steering effort may be heavy due to increased flow resistance of cold fluid. After warming-up engine, turn the steering wheel from stop to stop several times to warm-up the fluid. If steering effort reduces normally, the power steering is functioning normally.

*3 In cold weather or with insufficient warm-up of the engine, steering effort may be heavy due to excessive drop of idling when turning the steering wheel. In this case, it is recommended to start the vehicle by increasing engine speed a little higher than usual. If steering effort reduces normally, the power steering is functioning normally.

POWER ASSISTED SYSTEM (POWER STEERING)

1. ABNORMAL NOISE & VIBRATION

CAUTION:

Do not keep the relief valve operating for over 5 seconds at a time or the inner parts of the oil pump may be damaged due to rapid increase of fluid temperature.

NOTE:

• A screeching noise may be heard immediately after the engine start in extremely cold conditions. In this case, if the noise goes away when the vehicle warms up, the system is functioning normally. This is due to the fluid characteristics in extremely cold condition.

• The oil pump normally makes a small whining noise due to its mechanism. Even if a noise is heard when steering wheel is turned at stand still, there is no abnormal function in the system provided that the noise eliminates when the vehicle is driving.

- When turning the steering wheel with the brake applied when the vehicle is parked, a screeching noise may be generated by the brake disc and pads. This is not a fault in the steering system.
- There may be a small vibration around the steering devices when turning the steering wheel at standstill, even though the component parts are operating properly

Hydraulic systems are likely to generate this kind of vibration as well as working noise and fluid noise because of combined conditions, i.e., road surface and tire surface, engine speed and turning speed of the steering wheel, fluid temperature and braking conditions.

These conditions do not indicate a problem in the system.

Confirm vibration for an AT model, by applying the parking brake on a concrete surface, shifting into the "D" range, and turning the steering wheel repeatedly at from slow to rapid, step by step.

Trouble	Possible cause	Corrective action	
Hiss noise (continuous) While engine is running.	The relief valve emits an operating sound when steering wheel is completely turned in either direction. (Do not keep this condition over 5 seconds.)	Normal	
	Relief valve emits an operating sound when steering wheel is not turned. This means that the relief valve is defective.	Replace the oil pump.	
Rattling noise (intermittent) when engine is running.	Interference with adjacent parts	Check the clearance. <ref. to<br="">PS-54, INSPECTION OF CLEARANCE, INSPECTION, General Diagnostic Table.> Correct if necessary. <ref. inspection,<br="" ps-39,="" to="">Pipe Assembly.></ref.></ref.>	
	Loosened attachment of the oil pump, reservoir tank, pump bracket, gearbox or crossmember	Retighten.	
	Loose oil pump pulley or other pulley(s)	Retighten.	
	Looseness of the linkage, play in the steering, improper tightening (looseness) of suspension joints or steering col- umn	Retighten or replace.	
	Sound generates from the inside of gearbox or oil pump.	Replace faulty parts in the gear- box or oil pump.	
Knocking When turning steering wheel in	Excessive backlash Loosened lock nut for adjusting backlash	Adjust and retighten.	
both directions with small angle repeatedly at engine ON or OFF.	Insufficient tightening or play in the tie-rod or tie-rod end	Retighten or replace.	
Grinding noise (continuous) While engine is running.	Air in vane pump	Inspect and retighten the fluid line connection. Refill the fluid and vent air.	
	Vane pump seizing	Replace the oil pump.	
	Oil pump pulley bearing seized	Replace the oil pump.	
	Folded hose, flattened pipe	Replace.	
Squeal, squeak (intermittent or continuous) While engine is running.	Improper adjustment of pulley belt Damaged or over tensioned pulley belt Unequal length of pulley belts	Adjust or replace. (Replace two belts as a set.)	
	Runout or dirty V-groove surface of oil pump pulley	Clean or replace.	

General Diagnostic Table

POWER ASSISTED SYSTEM (POWER STEERING)

Trouble	Possible cause	Corrective action	
Sizzling noise (continuous) While engine is running.	Fluid aeration	Fix the faulty part causing aera- tion. Replace the fluid and vent air.	
	Damaged pipe of gearbox	Replace the pipe.	
	Faulty inside of hose or pipe Flattened hose or pipe	Repair or replace.	
	Problem inside the reservoir tank	Replace.	
	Missing reservoir tank cap	Install cap.	
Whistle (continuous) While engine is running.	Faulty pipe of gearbox or faulty hose	Replace the faulty parts of the gearbox or the hose.	
Whine or growl (intermittent or	Looseness of oil pump, oil pump bracket attachment	Retighten.	
continuous) While engine is running with/ without steering turned.	Fault inside of oil pump or hose	Replace the oil pump or hose, if the noise can be heard when vehicle is running as well as being stopped.	
	Torque converter growl, air conditioner compression growl	Remove the power steering pul- ley belt and check.	
Grinding noise (continuous) While engine is running with the steering turned.	Fault inside of gearbox	Replace the faulty parts of gear- box.	
	Faulty steering shaft bearing	Apply grease or replace.	
	Occurs when turning the steering wheel with brakes (service or parking) applied.	If the noise goes away when brake is released, it is normal.	
Vibration While engine is running with/ without steering turned.	Engine speed is too low.	Adjust, and notify customer.	
	Air in vane pump	Repair faulty part Vent air.	
	Damaged valve in oil pump or gearbox	Replace the faulty parts in gear- box and oil pump.	
	Excessive play in steering, looseness of suspension parts	Retighten.	

2. MEASUREMENT OF STEERING EFFORT

Step		Check	Yes	No
1	 CHECK STEERING EFFORT. 1) Stop the vehicle on paved road. 2) Start the engine. 3) Run the engine at idle. 4) Install a spring scale on the steering wheel. 5) Pull the spring scale at a right angle to the steering wheel, and measure both right and left steering wheel efforts. NOTE: When turning the steering more quickly than necessary from one direction to the other at an engine speed over 2,000 rpm, steering effort may be heavy. This is caused by flow characteristic of the fluid in the oil pump and is not a defect. 	Is the steering effort less than 29.4 N (3.0 kgf, 6.6 lb)?	Go to step 2.	Adjust the back- lash.
2	 CHECK STEERING EFFORT. 1) Stop the engine. 2) Pull the spring scale at a right angle to the steering wheel, and measure both right and left steering wheel efforts. 	Is the steering effort less than 314 N (35 kgf, 77 lb)?	Go to step 3.	Perform the adjust- ment.
3	 CHECK STEERING WHEEL EFFORT. 1) Remove the universal joint. 2) Measure the steering wheel effort. 	Is steering effort less than 2.26 N (0.23 kgf, 0.51 lb)?	Go to step 4.	Check, adjust and replace if neces- sary.
4	CHECK STEERING WHEEL EFFORT. Measure the steering wheel effort.	Is the steering effort difference in the left and right directions is less than 1.08 N (0.11 kgf, 0.24 lb)?	Go to step 5.	Check, adjust and replace if neces- sary.
5	CHECK UNIVERSAL JOINT. Measure the swing torque of the joint (yoke of steering column side). <ref. ps-14,<br="" to="">INSPECTION, Universal Joint.></ref.>	Is the swing torque of the universal joint less than 7.3 N (0.74 kgf, 1.64 lb)?	Go to step 6 .	Replace with a new part.
6	CHECK UNIVERSAL JOINT. Measure the swing torque of the joint (yoke of gearbox side). <ref. inspection,<br="" ps-14,="" to="">Universal Joint.></ref.>	Is the swing torque of the universal joint less than 7.3 N (0.74 kgf, 1.64 lb)?	Go to step 7.	Replace with a new part.
7	FRONT WHEEL CHECK. Check the front wheels.	Does the front wheels have unsteady revolution or rattling, or does the brakes drag?	Inspect, readjust and replace if nec- essary.	Go to step 8.
8	CHECK TIE-ROD ENDS. Remove the tie-rod ends.	Is there any unsteady revolu- tion or rattling of suspension tie- rod ends?	Inspect and replace if neces- sary.	Go to step 9.
9	BALL JOINT CHECK. Remove the ball joint.	Is there any unsteady revolu- tion or rattling of suspension ball joints?	Inspect and replace if neces- sary.	Go to step 10.
10	CHECK GEARBOX. Measure the rotating resistance of the gearbox. <ref. of<br="" ps-34,="" resistance="" to="" turning="">GEARBOX, INSPECTION, Steering Gearbox.></ref.>	Is the rotating resistance of steering gearbox less than 9.33 N (0.95 kgf, 2.09 lb)? Is the dif- ference between right and left sides less than 20%?	Go to step 11.	Readjust the back- lash, and if ineffec- tive, replace the faulty parts.
11	CHECK GEARBOX. Measure the sliding resistance of the gearbox. <ref. inspec-<br="" limit,="" ps-33,="" service="" to="">TION, Steering Gearbox.></ref.>	Is the sliding resistance of steering gearbox less than 304 N (31 kgf, 68 lb)? Is the differ- ence between the right and left sliding resistances less than 20%?	Steering effort is normal.	Readjust the back- lash, and if ineffec- tive, replace the faulty parts.

POWER ASSISTED SYSTEM (POWER STEERING)

3. INSPECTION OF CLEARANCE

This table lists various clearances that must be correctly adjusted to ensure the normal vehicle driving without interfering noise, or any other faults.

Install locations	Minimum allowance
(1) Crossmember to pipe	5 mm (0.20 in)
(2) DOJ to shaft or joint	14 mm (0.55 in)
(3) DOJ to valve housing	11 mm (0.43 in)
(4) Pipe to pipe	2 mm (0.08 in)
(5) Stabilizer to pipe	5 mm (0.20 in)
(6) Exhaust pipe to pipe	11 mm (0.43 in)
(7) Exhaust pipe to gear box bolt	15 mm (0.59 in)
(8) Side frame to hose A and B	10 mm (0.39 in)
(9) Cruise control pump — Hoses A and B	15 mm (0.59 in)
(10) Pipe portion of hose A to pipe portion of hose B	1.5 mm (0.059 in)

