DTC	62-47	High Temperature

DTC	63-47	High Temperature

DESCRIPTION

DTC No.	DTC Detecting Condition	Trouble Area
62-47	Sensor detects that CD unit temperature is high. (Over 80°C)	Radio receiver
63-47	Sensor detects that CD unit temperature is high. (Over 80°C)	

INSPECTION PROCEDURE

HINT:
After the inspection is completed, clear the DTCs.

1	CHECK RADIO RECEIVER

(a) Park the vehicle in a cool place.
(b) Check that the temperature of the radio receiver becomes sufficiently low, and start the engine. Check that the malfunction disappears.
OK:
Malfunction disappears.

NG → **REPLACE RADIO RECEIVER**

OK

END

DTC	62-78	DSP Error

DTC	63-78	DSP Error

DESCRIPTION

DTC No.	DTC Detecting Condition	Trouble Area
62-78	An error occurs during the decode process (MP3/ WMA).	-
63-78	An error occurs during the decode process (MP3/ WMA).	-

INSPECTION PROCEDURE

HINT:
After the inspection is completed, clear the DTCs.
NOTICE:
- **These codes may be output even if there is no malfunction.**
- **If these codes are output frequently, replace the radio receiver.**

1	CLEAR DTC

(a) Clear the DTCs (See page AV-18).

NEXT

AV

2	RECHECK DTC

(a) Recheck for DTCs and check if the same trouble occurs again.
OK:
Malfunction disappears.

NG → REPLACE RADIO RECEIVER

OK

END