## **SYMBOLS**

The following symbols are used in the Welding Diagrams in Section RE of this manual to indicate cutting areas and the types of weld required.

SYMBOLS	MEANING	ILLUSTRATION
	SAW CUT OR ROUGH CUT	
///////////////////////////////////////	REMOVE BRAZE	
	WELD POINTS  SPOT WELD OR MIG PLUG WELD  (See page IN-5)	
***************************************	CONTINUOUS MIG WELD (BUTT WELD OR TACK WELD)	
<b>~~~~~~</b>	BRAZE	
	BODY SEALER	

## **Illustration of Weld Point Symbols**

## **EXAMPLE:**

