

SERVICE BULLETIN

OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN				No.: MSB-97E26-002		
				Date: 1997-09-26	<model></model>	<m y=""></m>
Subject:	ADDITION OF FRONT AXLE SHAFT			E SHIM TO DRIVE	(EC,EXP)COLT (CJ0A)	96-10 96-10
Group:	FRONT AXLE DI		Dra	aftno: 97-TA-003	(EC,EXP)LANCER (CK0A)	93-10
INFORMATION		OVERSEAS SERVICE DEPT		R. Usami R. USAMI - MANAGER QUALITY INFORMATION ANALYSIS	(EC,EXP) LANCER WAGON(CB0W)	

1. Description:

The front axle shim has been added to the axle hub end of the front drive shaft. This has bought about a change in the Disassembly steps.

Front axle shim
9 11M0072

2. Effective Date:


- Colt/Lancer (CJ/CK) From November 11, 1996
- Lancer Wagon (CB) From January 17, 1997


3. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
'96 COLT/LANCER Workshop Manual	PWME9511	(English)	26-14
chassis	PWMS9512	(Spanish)	
	PWMF9513	(French)	
	PWMG9514	(German)	
	PWMD9515	(Dutch)	
	PWMW9516	(Swedish)	
COLT/LANCER Workshop Manual	PWME9117-A	(English)	26-16, 26-25
chassis	PWMS9118-A	(Spanish)	
	PWMF9119-A	(French)	
	PWMG9120-A	(German)	
	PWMD9121-A	(Dutch)	
	PWMW9122-A	(Swedish)	
4. Details:			

'96 COLT/LANCER Workshop Manual chassis, Page 26-14 COLT/LANCER Workshop Manual chassis, Page 26-16 COLT/LANCER Workshop Manual chassis, Page 26-25

DISASSEMBLY AND REASSEMBLY






2. for vehicles with ABS, be careful not to damage the rotors installed to the R.J> (or B.J.) outer race during disassembly and reassembly.

*1: <1300, 1600> *2: <1800, 2000D>

DISASSEMBLY AND REASSEMBLY

E260E-2

26-25



- 8. Dust seal outer
- 9. Dust seal inner
 - 10. Center bearing
 - 11. Center bearing bracket

- Do not disassemble the B.J. assembly
 For vehicles with ABS, be careful not to damage the rotors installed to the R.J. (or B.J.) outer tace during disassembly and reassembly

<Revised>