

Service Bulletin List

No.	Subject	Date
MSB-97E23-501	ROAD TEST JUDGEMENT VALUE	1997-11-24
MSB-97E26-002	ADDITION OF FRONT AXLE SHIM TO DRIVE SHAFT	1997-09-26
MSB-97E37-001	CHANGE IN POWER STEERING HOSE PIPING	1997-07-15
MSB-97E52-001	ADDITION OF SRS AIR BAG MAINTENANCE PROCEDURE	1997-04-30
MSB-97E52-501	CORRECTION TO CAUTION ON AIR BAG MODULE AND CLOCK SPRING	1997-11-24
MSB-97E55-001	CHANGE IN AIR GAP FOR A/C COMPRESSOR	1998-04-15
MSB-97E55-501	RECTIFYING OMISSIONS AND ERRORS IN EVAPORATOR INSTALLATION AND REMOVAL	1997-07-15
MSB-98E00-503	CORRECTION TO DIAGNOSIS CODE READING PROCEDURE FOLLOWED WHEN USING WARNING LAMP	1998-12-15
MSB-98E23-503	ADDITION/CORRECTION OF HYDRAULIC PRESSURE TEST OF AUTOMATIC TRANSMISSION	1999-05-05
MSB-98E52-502	CORRECTION TO ERASING OF DIAGNOSIS CODES	1999-10-31