TRAILER HITCH WELD CAN BREAK: NEW TRAILER HITCH

1991 Mitsubishi Montero

NHTSA RECALL BULLETIN

Models: 1986 Isuzu Trooper II 1987 Dodge Raider 1987 Isuzu Trooper II 1988 Dodge Raider 1988 Isuzu Trooper II 1989 Dodge Raider 1989 Isuzu Amigo 1989 Isuzu Trooper II 1990 Isuzu Amigo 1990 Isuzu Trooper 1991 Isuzu Amigo 1991 Isuzu Trooper 1991 Mitsubishi Montero 1991 Toyota Land Cruiser 1992 Mitsubishi Montero 1992 Toyota Land Cruiser 1993 Toyota Land Cruiser

Number of Affected Vehicles: 670

Reginning Date of Manufacture: 199

Beginning Date of Manufacture: 1992 MAR Ending Date of Manufacture: 1993 JUN

FAULT:

Weld, Solder broken

SYSTEM:

Trailer hitch.

EQUIPMENT DESCRIPTION:

Reese class II trailer hitch, Part No. 06070.

DESCRIPTION OF DEFECT:

The weld on the receiver unit of the trailer hitch can break.

CONSEQUENCE OF DEFECT:

If the failure occurs, the trailer can separate from the towing vehicle, and could result in a vehicle crash without warning.

CORRECTIVE ACTION:

Replace the trailer hitch.

NOTE:

If your vehicle is presented to the dealer from whom you purchased the item on an agreed service date and the remedy is not provided or the remedy does correct the safety-related defect or noncompliance, please contact Reese Products warranty department at 1-800-326-1090, ext. 203. Also contact the National Highway Traffic Safety Administration's auto safety hotline at 1-800-424-9393.

ADDITIONAL INFORMATION:

The National Highway Traffic Safety Administration operates Monday

through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.