## INTERFERENCE VERIFICATION CHECK FOR OHC ENGINE

#### 1993 Mitsubishi Montero

Maintenance & Service Information 1983-96 Mitsubishi - Timing Belt Information

Cordia, Diamante, Eclipse, Expo, Expo LRV, Galant, Mirage, Montero, Pickup, Precis, Sigma, Tredia, Van, 3000GT

# TIMING BELT INTERFERENCE VERIFICATION INFORMATION

#### TIMING BELT INTERFERENCE CAUTION

NOTE:

CAMSHAFT DRIVE BELTS OR TIMING BELTS - The condition of camshaft drive belts should always be checked on vehicles which have more than 50,000 miles. Although some manufacturers do not recommend replacement at a specified mileage, others require it at 60,000-100,000 miles. A camshaft drive belt failure may cause extensive damage to internal engine components on most engines, although some designs do not allow piston-to-valve contact. These designs are often called "Free Wheeling". Many manufacturers changed their maintenance and warranty schedules in the mid-1980's to reflect timing belt inspection and/or replacement at 50,000-60,000 miles. Most service interval schedules shown in this section reflect these changes. Belts or components should be inspected and replaced if any of the following conditions exist:

- \* Crack Or Tears In Belt Surface
- \* Missing, Damaged, Cracked Or Rounded Teeth
- \* Oil Contamination
- \* Damaged Or Faulty Tensioners
- \* Incorrect Tension Adjustment

# TIMING BELT INTERFERENCE CHECK MENU

## TIMING BELT INTERFERENCE VERIFICATION TABLE (1)

Applicatio	on	Engine	Replacement Ir	nterval (Miles)
Passenger Cordia	Cars			
1983-88				•
Diamante 1992-96				60,000 60,000
		1.8L 4-Cyl ) 2.0L 4-Cyl. )L 4-Cyl. Non-T 2.0L 4-Cyl. Tur 2) 2.4L 4-Cyl.		60,000 60,000 60,000 60,000 60,000
Expo 1992-95				60,000 60,000
Expo LRV 1995		1.8L 4-Cyl 2) 2.4L 4-Cyl.		60,000 60,000

1985-87 1988 1989-93	(2) 2.4L 4-Cyl. (4) 	60,000 60,000 60,000 60,000 60,000
Mirage 1985-96 1985-88 1989, 19 1993-96 Precis	(2) 1.5L 4-Cyl	60,000 60,000 60,000 60,000
1987-93	(2) 1.5L 4-Cyl	60,000
Sigma 1989-90	3.0L V6 (3)	60,000
Tredia 1983-88	1.8L 4-Cyl. (4) 2.0L 4-Cyl. (4)	•
3000GT 1991-96	(2) 3.0L V6	60,000
Light Truc Montero	ks	
1985-96 1994-96	3.0L V6	60,000 60,000
Pickup 1983-89 1983-86 1990-96		60,000 60,000
Van 1987-90	2.4L 4-Cyl (4)	60,000

- (1) Other interference engine applications may exist which are not indicated here.
- (2) Interference engine. Check for possible damage to piston(s) or valve(s) if there has been a timing belt failure.
- (3) Although the vehicle manufacturer does not recommend a specific scheduled maintenance interval, aftermarket belt manufacturers suggest the belt be replaced at 60,000 mile intervals.
- (4) Vehicle manufacturer recommends replacing all belts at the same time.