

## SERVICE BULLETIN

**APPLICABILITY** 92MY LEGACY

**DATE** 01-17-92

**SUBJECT:** 92MY LEGACY READ MEMORY CONNECTOR LOCATION

The read memory connector is being relocated to the right side of the steering column near the select monitor connector.

Because of production limitations not all 1992 Legacys will have the read memory connector in the new location, so it may be necessary to look in both areas to locate it.

The location of the test mode connector (green) is not changed.

### CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS. Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.