

SERVICE BULLETIN

APPLICABILITY

LEGACY

DATE

09-16-92

SUBJECT:**LEGACY SERVICE MANUAL CORRECTIONS
FOR ABS TROUBLE CODES SECTION 4****1992 Legacy Service Manual Section 4****Trouble Code 0**

- o Eliminate Step 4 on Page 94. This step has been found to be unnecessary. Eliminate Step 4 of trouble tree on Page 92.

Add to all Legacy Service Manuals in Section 4.**Trouble Code 16, Step 4**

- o Check all wheel sensors for physical damage, corrosion, open and shorts.
- o See Trouble Codes for wheel sensors.

1991 and 1992 Legacy Service Manual Section 4**Trouble Code 9**

- o Add to Step 1 a new specification of 72-88 for 1991 and later vehicles, starting with VIN 607163 Sedan and VIN 902970 Wagon.

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.