

SERVICE BULLETIN

APPLICABILITY

1990, 1991, 1992 LEGACY

DATE

09-16-92

SUBJECT:**SERVICE MANUAL CORRECTIONS**

PLEASE BE ADVISED THAT CODES 13, 14, 23, and 24 of the passive seat belt system lists connector R42 terminal #5 and body as having 10-13 volts. This information is incorrect.

Make corrections to 5-3, Item4, step 4, to read:

Connector R42 terminal #3 and Body as having 10-13 volts for each code listed above.

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS. Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.