

insider info.

Knocking Or Tapping Noise: 2.5 Liter Engine

Before condemning a 2.5 liter engine for having an engine knock or a valve tap, make certain that all the spark plug wires are firmly connected to their corresponding spark plugs. The spark plugs are deeply recessed in the cylinder heads, so the sound that is produced by a loose plug wire can easily be confused with valve tap or piston slap.