

BODY ELECTRICAL SYSTEM

BE01E-11

PRECAUTION

Carefully to observe the following precautions when servicing the parts related to the body electrical system.

1. LIGHTING SYSTEM

Halogen bulbs have pressurized gas inside and require special handling.

They can burst or scatter if scratched or dropped. Hold a bulb only by its plastic or metal case. Do not touch the glass part of a bulb with bare hands.

2. SRS (SUPPLEMENTAL RESTRAINT SYSTEM)

The TOYOTA TUNDRA is equipped with the Supplemental Restraint System (SRS) (for example, the driver airbag). Failure to carry out service operations in the correct sequence could cause the SRS to unexpectedly deploy during servicing, possibly leading to a serious accident. Before servicing (including removal, installation, inspection and replacement), be sure to read the precautionary notices in the RS section.

3. AUDIO SYSTEM

If the battery negative (–) terminal is disconnected, the preset AM, FM 1 and FM 2 stations stored in the memory are erased. Be sure to make a note of the stations and reset them after the battery terminal is reconnected.

4. MOBILE COMMUNICATION SYSTEM

If the vehicle is equipped with a mobile communication system, refer to the precautions for the mobile communication system in the IN section.