



For JBS Units without  
On-board Door Lock Relays:

Requires  
(1) 778 or  
(2) 775's



For JBS Units with On-board Door Lock Relays:



KE-100, KE-150 and 1702

