



SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS
OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN		No.: MSB-99E11-502	
		Date: 1999-11-15	<Model> (EC) PAJERO <M/Y> 97-10 (V10,V20,V30,V40)
Subject:	CORRECTION OF 4M40 ENGINE IDLE UP SPEED (FOR ANTI-SKID BRAKE)		
Group:	ENGINE	Draft No.: 98-SY-610211	
INFORMATION	INTERNATIONAL CAR ADMINISTRATION OFFICE	 T.NITTA - PROJECT LEADER AFTER SALES SERVICE & CS PROMOTION	

1. Description:

This service bulletin informs you of correction of 4M40 Engine Idle up speed (For Anti-Skid brake).

2. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
'97 PAJERO	PWJE9086-H	(English)	
Workshop Manual	PWJS9087-H	(Spanish)	
SUPPLEMENT	PWJF9088-H	(French)	
	PWJG9089-H	(German)	
	PWJD9090-H	(Dutch)	
	PWJW9091-H	(Swedish)	

3. Effective Date:

'97, '98 model year

4. Details:

Refer to the attached sheets.

ENGINE

GENERAL OUTLINE OF CHANGES

Idle up speed (For Anti-Skid Brake) of 4M40 engine was changed.

SPECIFICATIONS SERVICE SPECIFICATIONS

Items	Standard value	
Idle up speed (for anti-skid brake) r/min.	1500 ± 50	('97, '98 Model Year)

ENGINE <4M40> SERVICE ADJUSTMENT PROCEDURE THROTTLE OPENER INSPECTION AND ADJUSTMENT - FOR ABS

Inspection and adjustment service points are the same as before.

Only the standard value has changed.

Standard value: 1200 ± 50 r/min (~'96 model year)

Standard value: 1500 ± 50 r/min (~ '97, '98 model year)