

Service Bulletin List

No.	Subject	Date
MSB-97E26-001	CHANGE OF FRONT ROTOR FOR ABS EQUIPPED VEHICLES (REVISED)	1997-12-05
MSB-97E37-003	CHANGE IN TIE ROD NUT TIGHTENING TORQUE VALUES	1998-01-16
MSB-97E52-001	ADDITION OF SRS AIR BAG MAINTENANCE PROCEDURE	1997-04-30
MSB-98E00-011	CHANGE IN YEAR MODEL FOR '99 PAJERO	1998-10-15
MSB-98E27-001	CHANGE OF ABS REAR ROTOR	1998-06-15
MSB-98E37-002	NEW SERVICE PROCEDURE FOR POWER STEERING GEARBOX	1999-08-15
MSB-98E42-502	CORRECTING MINIMUM ENTRAPMENT AMOUNT FOR POWER WINDOW WITH SAFETY MECHANISM	1998-11-30
MSB-98E54-002	CORRECTION TO ELC 4-SPEED AUTOMATIC TRANSMISSION CIRCUIT	1998-11-30
MSB-99E11-502	CORRECTION OF 4M40 ENGINE IDLE UP SPEED (FOR ANTI-SKID BRAKE)	1999-11-15
MSB-99E16-001	CHANGE OF GLOW PLUG	2000-04-15
MSB-00E31-001	WHEEL BALANCE ADJUSTMENT PROCEDURE	2000-07-15
MSB-00E35-001	CHANGE TO ERASING OF ABS DIAGNOSTIC CODES	2000-05-30
MSB-00E37-501	ADDITION OF STEERING ANGLE ADJUSTMENT PROCEDURE	2000-12-30