SUBARU®

NUMBER 16-48-91

SERVICE BULLETIN

APPLICABILITY LOYALE, XT AND LEGACY WITH 4EAT AFTER TRANSMISSION NUMBER 136395

DATE 05-15-91

SUBJECT: 4EAT SLOW ENGAGEMENT

Service Bulletin Number 16-36-90, dated 2/26/90, describes a field fix for 4EAT slow engagement caused by torque converter drain down.

This Bulletin also gives information for a production change starting with Transmission Number 136395 which eliminates torque converter drain down.

Installation of the field fix kit into a transmission which already has the production modification, will severely restrict fluid flow and cause severe damage to the transmission components.

Make sure you check the transmission number before installing the field fix kit. Damage to the transmission caused by this improper repair is not a matter for Warranty.

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.