TOYOTA SERVICE BULLETIN

Group: 03 No.: 04 Date: Feb, 19

Model: Aurion (GSV40)

Subject: Corrections to Repair Manual RM02N2EQ

Please ensure these pages are distributed to all relevant staff for their information; and a copy made available for future reference, with the above repair manual.

Section	Title	Paragraph
2GR-FE EXHAUST	EXHAUST PIPE	COMPONENTS

The revised pages listed above are attached.


(The corrected parts are indicated by arrows.)

This bulletin does not cause the Flat Rate Manual to be changed

© 2019 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.

EXHAUST PIPE

COMPONENTS



© 2019 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.