COMBINATION METER (From August, 2004)

PROBLEM SYMPTOMS TABLE

710Q1–01

Buzzer:

Symptom	Suspected Area	See page
6 M/T reverse buzzer does not operate.	1. Wire Harness or Connector 2. Combination Meter Assy	– 71–25 (*1)

HINT:

*1: Refer to repair manual RM990E