DTC	P0A37/258	GENERATOR TEMPERATURE SENSOR CIRCUIT RANGE/PERFORMANCE

CIRCUIT DESCRIPTION

Refer to DTC P0A38 (INF 257) on page 05–344.

DTC No.	INF Code	DTC Detection Condition	Trouble Area
P0A37	258	Motor temperature sensor No. 2 malfunction	• Hybrid vehicle motor

INSPECTION PROCEDURE

If the information (INF) code 258 is present, replace the hybrid vehicle motor.

HINT:

The motor temperature sensor No. 2 is unavailable as an individual service part. Therefore, when replacing it, the hybrid vehicle motor must be replaced.

REPLACE HYBRID VEHICLE MOTOR ASSY