05I9E–01

PROBLEM SYMPTOMS TABLE

Problem Symptom	Suspected Area	See Page
Hybrid control system does not start	1. ECU power source circuit	05–2081
	2. Transponder key ECU assy	05–2081
	3. Push button start system	05–2121