PRIUS

OUTLINE OF NEW FEATURES

The following changes are made for the 2008 model year.

1. Tire Pressure Warning System

- In the tire pressure warning system, the following items have been changed.

Changed Item	’08 Prius	’07 Prius
Time required for the tire pressure warning ECU to determine a malfunction in the tire pressure warning valve and transmitter	20 minutes	51 minutes
The blinking of the tire pressure warning light between the registration of the ID code of the tire pressure warning valve and transmitter and the normal operation of the system	Turns ON after blinking for 1 minute	—

- The following DTCs (Diagnostic Trouble Codes) are added.

DTC Code	Detection Item
C2126/26	Transmitter ID not Received in Main Mode
C2179/79	Communication is interrupted (for BEAN)