



**Technical Service
BULLETIN**

September 9, 2003

Title:
TRIM GARNISH LOOSE
Models:
All Models

TSB

REVISED

B0017-03

BODY

TSB REVISION NOTICE:

March 3, 2004: The TSB has been changed to include new inspection and replacement instructions.
Previous versions of this TSB should be discarded.

Introduction Customers may experience an interior trim panel either loose or fitting poorly due to a deformed or missing panel attachment clips. When a trim garnish (A, B, C or D pillar garnish, door trim panel, etc.) is removed and reinstalled using the old clips, there is a possibility that the garnish may exhibit a loose condition. To prevent this condition from occurring, please use the following procedures.

Inspection/Replacement Procedure **All Models** – All trim panel attachment clips must be inspected prior to reassembly and replaced if any damage or wear is detected. If no damage is visible, the clip may be reused. Always check to make sure that the garnish is properly attached after reinstallation of all interior trim panels.

2002 – 2004 model year Camry and 2004 model year Solara – When removing the A-pillar garnish panels, replace the white plastic attachment clips (P/N 90467–A0025).

Applicable Vehicles • **All models.**

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

