SYSTEM WIRING DIAGRAMS
3.0L, Engine Performance Circuits, California (3 of 3)
1997 Mitsubishi Montero Sport

For DIAKOM-AUTO http://www.diakom.ru Taganrog support@diakom.ru (8634)315187

Copyright © 1998 Mitchell Repair Information Company, LLC

Thursday, December 14, 2000 05:28PM