










Position of Parts in Instrument Panel <LHD>




H 99	Junction Connector
H 100	Junction Connector
H 101	Junction Connector
H 102	Junction Connector
H 103	Junction Connector
H 104	Junction Connector
H 105	Junction Connector
H 106	Junction Connector
H 107	Junction Connector
H 108	Junction Connector
H 109	Junction Connector
H 110	Junction Connector
H 111	Junction Connector
H 112	Junction Connector
H 113	Junction Connector
H 114	Fuse Block
H 117	Junction Connector
H 118	Junction Connector
H 119	Junction Connector
H 120	No. 1 Stereo Jack Adapter Assembly

Position of Parts in Instrument Panel <LHD>




Position of Parts in Instrument Panel <LHD>

H118
White



H119
White



H120
Black

