
(BAT)
7. 5A
STOP
(BAT)
7. 5A
STOP
(BAT)
100A
P/I
ALT
(BAT)
50A
P/I–B
NO. 1 (*3)
40A
P/I–B
NO. 1 (*4)
(IG)
10A
LH–IG
IC1
GND
A5
Stop Light Switch Assembly
ALT
BATT
IG1A
RELAY INTEGRATION
STP0
GNDA
GNDB
STOP
A92
Junction
Connector
A51(A), A75(B)
Junction
Connector
A69
Junction
Connector
A68
Junction Connector
A7
N1
N3
A2
A2
A1

∗ 1 : 6–Speed A/T
∗ 2 : 8–Speed A/T
∗ 3 : Before Oct. 2015 Production
∗ 4 : From Oct. 2015 Production



＊4 : From Oct. 2015 Production



A 5
White



A 51
Blue



A 68
Gray



A 69
Gray

A 75
White



A 92
Gray



T 44
Blue



T 45
Blue



U 20
Black



U 27
White



U 43
White



U 45
White



U 52
Blue



U 53
Blue



U 65
White



a 11
White



a 12
White



a 14
White



1C



2A
Black



2B
Black



2E
White



2F
White



2G
Black



4A
White



4D
White



5B
White



5C
White



5D
White



6A
White



6B
White



TU1
White






aT1
White
1 2 3 4 5 6 7 8 9 10 11 12 13 14
15 16 17 18 19 20 21 22 23 24 25 26
14 13 12 11 10 9 8 7 6 5 4 3 2 1
26 25 24 23 22 21 20 19 18 17 16 15