


MULTIPLEX COMMUNICATION SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

DI2AT-12

Perform troubleshooting in accordance with the procedure on the following page.



*

System		See page
Engine	2JZ-GE engine	★ DI-24
	3UZ-FE engine	DI-93
Body No.1 control system		DI-604
Body No.2 control system		★ DI-660
Driver door system		DI-634
Passenger door system		DI-668
Rear right door system		DI-717
Rear left door system		DI-697
Air conditioning system		★ DI-912
Power Tilt and Power Telescopic Steering Column		★ DI-356
Combination meter system		★ DI-584
Sliding roof system		★ DI-604
Power seat system		★ DI-522
LEXUS navigation system		DI-848

★ : LEXUS GS300 Repair Manual Pub. No. RM588E

Step 4, 8 : Diagnostic steps permitting the use of the LEXUS hand-held tester.