


Position of Parts in Instrument Panel (From Aug. 2013 Production)




*4:w/ Climate Control Seat w/ Seat Heater
 *5:w/o Climate Control Seat w/ Seat Heater
 *6:w/ Climate Control Seat w/o Seat Heater
 *7:Before Nov. 2017 Production
 *8:From Nov. 2017 Production


Position of Parts in Instrument Panel (From Aug. 2013 Production)

i1	No. 1 Indoor Electrical Key Antenna Assembly
i2	Power Point Socket Assembly
i3	Refreshing Seat Switch RH
i4	Refreshing Seat Switch LH
i5	Combination Switch Assembly
i6	Refreshing Seat Switch RH
i7	Refreshing Seat Switch LH
i8	Refreshing Seat Switch RH
i9	Refreshing Seat Switch LH
x1	Hazard Warning Signal Switch Assembly
z1	A/C Amplifier Assembly , A/C Blower Assembly
z5	Driver Side Squib Circuit , Spiral Cable Sub-Assembly
z6	Driver Side Squib 2nd Step Circuit , Spiral Cable Sub-Assembly
z7	Cruise Control Main Switch , Spiral Cable Sub-Assembly
z8	Spiral Cable Sub-Assembly , Steering Pad Switch Assembly
z9	Spiral Cable Sub-Assembly , Steering Wheel Heater Control Assembly
z10	Cup Holder Illumination RH (No. 1 Interior Illumination Light Assembly)
z11	Cup Holder Illumination LH (No. 1 Interior Illumination Light Assembly)
z12	A/C Amplifier Assembly , A/C Blower Assembly


Position of Parts in Instrument Panel (From Aug. 2013 Production)




90980-12795




90980-11299




90980-12552




90980-12552




90980-12553




90980-12552




90980-12552




90980-12551




90980-12551




82824-21030




90980-12264




90980-12224




90980-12219






90980-12360



90980-12361



90980-10795



90980-12551