







Seat Heater <Rear Passenger's Seat , From Sep. 2012 Production>






































Note :
Please refer to the Multiplex Communication System (CAN) section
for information regarding the shielded communication lines.






Seat Heater <Rear Passenger's Seat , From Sep. 2012 Production>






RS2
White



Rf1
White



zS7
White

