
3. COMPONENTS

(a) FRONT BUMPER




CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32812

(b) REAR BUMPER




CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32813


(c) INSTRUMENT PANEL



CAUTION:
The bolts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32814




CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32815


(d) INTERIOR TRIM



CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque ● Non-reusable part

F32817




CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.


N·m (kgf·cm, ft.·lbf) : Specified torque

F32818


w/o Deck Board:




w/ Deck Board:



F32819


x 5
ROOF HEADLINING ASSEMBLY
REAR ASSIST GRIP ASSEMBLY
COAT HOOK
ASSIST GRIP SUB-ASSEMBLY
ASSIST GRIP PLUG
ASSIST GRIP PLUG
COAT HOOK
ASSIST GRIP PLUG
ASSIST GRIP PLUG
REAR ASSIST GRIP ASSEMBLY
ASSIST GRIP PLUG
VISOR ASSEMBLY RH
ASSIST GRIP SUB-ASSEMBLY
NO. 1 ROOM LIGHT ASSEMBLY
x 2
MAP LIGHT ASSEMBLY
VISOR ASSEMBLY LH
x 2
VISOR HOLDER
DRIVE MONITOR SWITCH
x 2
VISOR BRACKET COVER LH
VISOR BRACKET COVER RH
VISOR HOLDER
w/ EC Mirror:
w/ Rear Monitor:
INNER REAR VIEW MIRROR STAY HOLDER COVER
w/o Rear Monitor:
INNER REAR VIEW MIRROR STAY HOLDER COVER
F32820

(e) FRONT SEAT




CAUTION:
The bolts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32816

(f) REAR SEAT

for 60/40 Split Double-folding Seat Type:




CAUTION:
The bolts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32821

for 60/40 Split Slide Walk-in Seat Type:




CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32822

for Rear No. 2 Seat:



CAUTION:
The bolts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F32823