

F RELAY LOCATIONS




: Center Connector


LHD : Left Side of the Instrument Panel Reinforcement (See Page 21)

RHD : Right Side of the Instrument Panel Reinforcement (See Page 21)


(LHD)



(RHD)



Unit A



Unit B

