EMISSION CONTROL

PREPARATION

020W4–01

Equipment

Service Wire Harness	
Ohmmeter	
Torque wrench	
Hand–held vacuum pump	