STARTING & CHARGING



020WB–01

PREPARATION

SST

	09249–63010	Torque Wrench Adaptor	GENERATOR ASSY(1AZ–FE) GENERATOR ASSY(2AZ–FE)

Recomended Tools

	(09083–00150)	Test Lead Set	STARTING SYSTEM(1AZ–FE) STARTING SYSTEM(1MZ–FE) STARTING SYSTEM(2AZ–FE)
	09216–00021	Belt Tension Gauge	GENERATOR ASSY(1MZ–FE)

Equipment

Ammmeter(A)	
Ohmmeter	
Torque wrench	