COMBINATION METER

HOW TO PROCEED WITH TROUBLESHOOTING

05651–01

1	Vehicle Brought to Workshop
2	Customer Problem Analysis (See page 05–1169)
3	Problem Symptom Confirmation (See page 05–1180)
4	Circuit Inspection (See page 05–1181 – 05–1222)
5	Repair or Replace
6	Confirmation Test
7	End