
REAR COMBINATION LAMP LENS LH

650C9–01

REPLACEMENT



1. REMOVE REAR COMBINATION LAMP LENS LH

(a) Remove the service hole cover.
(b) Remove the 3 nuts and disconnect the connector of rear combination light.
(c) Pull the rear combination light assy to the back of the vehicle, and remove the rear combination light assy.