
LAMP ASSY,SIDE TURN SUGNAL

650CC–01

REPLACEMENT

1. REMOVE LAMP ASSY,SIDE TURN SUGNAL



(a) Pull the side turn signal light lens RH as shown in the illustration.

(b) Disconnect the connector of side turn signal light and remove the socket.