NAVIGATION RECEIVER ASSY


REPLACEMENT

6709D–01

HINT:

COMPONENTS: See page 67–1

1. **REMOVE AIR CONDITIONER CONTROL ASSEMBLY(See page 71–10)**
2. **REMOVE INSTRUMENT CLUSTER FINISH PANEL SUB–ASSY CENTER (See page 71–10)**




3. **REMOVE NAVIGATION RECEIVER ASSY**

(a) Insert a screwdriver at indicated point and remove the navigation receiver assy from instrument cluster finish panel sub–assy.


HINT:

Tape the screwdriver tip before use.



4. **REMOVE RADIO RECEIVER BRACKET NO.1**

(a) Remove the 4 screws and radio receiver bracket No.1.



5. **REMOVE RADIO RECEIVER BRACKET NO.1**

(a) Remove the 4 screws and radio receiver bracket No.1.