73080–02

PROBLEM SYMPTOMS TABLE

Symptom	Suspected Area	See page
Key unlock warning buzzer does not sound	1. Unlock warning switch	73–19
	2. Front door courtesy lamp switch	73–19
	3. Instrument panel J/B (Body ECU)	73–16
	4. Combination meter	–
	5. Wire harness	–