
# FRONT CROSSMEMBER (ASSY)




F25705A

Symbol meaning

| | | |
|---|---|---|
| REMOVAL | A M A : Remove Weld Points | : Cut with disc sander, etc. |
| INSTALLATION | O M I : MIG Plug Weld | : Tack Weld |

F25705B

## REMOVAL·INSTALLATION




mm (in.)

F25705

## INSTALLATION POINT

1 Inspect the fitting of the related parts around the new parts before welding. This affects the appearance of the finish.
2 Temporarily install the new parts and measure each part of the new parts in accordance with the body dimension diagram. (See the body dimension diagram)
3 After applying the top coat, apply anti-rust agent to the internal panel portion of the closed section structural weld points.