
ENHANCEMENT OF PRODUCT APPEAL


■ PARTS WITH LOW REPAIR COST

- The plating portion of the front grille of 2GR-FE engine models has been redesigned as an individual part. As a result, replacing only damaged parts is possible, reducing repair costs.



025BO23Y

- By reducing from 18 to 8 the number of fixing points used for installing the rear bumper cover onto the vehicle body, repair time has been shortened.



025BO24Y

BO