INTRODUCTION

OUTLINE OF NEW FEATURES

The following changes have been made for the new Coaster.

1. Model Line-up

- The Singapore package models provided for XZB50R-ZEPQY have been discontinued.
- The newly added and discontinued models are shown in the table below.

Destination	Newly Added Model Code	Destination	Discontinued Model Code
G.C.C. Countries	● TRB50L-ZXMSKV ● HZB50L-ZXMSSV	Europe	● XZB50R-ZRMRYW1 ● XZB50L-ZRMRYW1 ● XZB50L-ZRMSYW1
General Countries	● HZB50L-ZXMSS ● XZB40L-BRMRY ● XZB40L-BRMSY ● XZB50L-ZGMRY ● XZB50L-ZGMSY ● XZB50L-ZXMSY	General Countries	● BB42R-ZRMSS ● BB42L-ZRMSS ● BB50L-ZGMSW ● BB50L-ZGMRW
Hong Kong	● BZB50R-ZCMSC5	Hong Kong	● BZB50R-ZCMSC

2. Exterior

Dark gray colored side window glasses have been provided for the models for Australia as the standard equipment.

3. Interior


- The settings and specification of the inside trim has been changed. For details, see page 7.
- The settings of the curtain have been changed. For details, see page 7.
- For some specification models, a room partition net assembly has been provided for securing cargos in the luggage space. For details, see page 8.

4. Engine


- The 2TR-FE engine with a leaded gasoline specification has been discontinued.
- The 15B-FT engine has been discontinued.
- A new N04C-VL engine has been adopted. For details, see page 9.

5. Suspension

- A low-pressure (N_2) gas type front shock absorber assembly with a multi-leaf type liner control valve has been adopted for the models for Taiwan and Australia, offering both driving stability and riding comfort.




New




Previous

- A low-pressure (N_2) gas type rear shock absorber assembly with a multi-leaf type liner control valve has been adopted for the models for Taiwan and Australia, offering both driving stability and riding comfort.



New



Previous

6. Body Structure

- A newly designed No. 1 engine under cover has been adopted. For details, see page 59.
- A center floor strength has been added to the models for Australia. For details, see page 60.

7. Seat

The settings and specification of the seat has been changed. For details, see page 61.

8. Seat Belt

For some models, the settings and specification of the seat belt has been changed. For details, see page 67.

9. Air Conditioning

- The position of a rear heater assembly for the models for Australia has been changed. For details, see page 70.
- For the models with a cooler box assembly, the settings and specification of a cooler box assembly has been changed. For details, see page 71.


10. Audio System

A newly designed audio head unit has been adopted. For details, see page 72.



0478BE03

New




0478MO07

Previous

11. Antenna


An antenna cord sub-assembly has been provided for separating the antenna cable into two.



0478MO05

Antenna Cord Sub-assembly

New



0478MO06

Previous

12. Rear View Monitor System

A rear television camera assembly for taking vehicle rear images has been provided for the models for Australia as the standard equipment. For detail, see page 76.