PRECAUTIONS

PR03D-01
Be careful not to grip the propeller shaft tube too tightly in the vise as this will cause deformation.

TROUBLESHOOTING

PR03E-01
Use the table below to help you find the cause of the problem. The numbers indicate the prioroty of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

PR

See Page / Parts Name / Trouble	PR-10	PR-9	PR-10	PR-10	PR-10	PR-11
	Sleeve yoke spline worn	Center bearing worn	Propeller shaft runout	Propeller shaft imbalance	Sleeve yoke spline stuck	Spider bearing worn or stuck
Noise	2	1				3
Vibration			2	3	1	

V03339