PP19C–03

EQUIPMENT

Dial indicator	Commutator
Pull scale	Brush spring
Sandpaper	Commutator
Torque wrench	
V–block	
Vernier calipers	Commutator Brush