

Tachograph
Condenser Fan
Power Source
15A DOME
10A GAUGE
J4 Junction Connector
J10(A), J11(B) Junction Connector
T3 Tachograph
J3 Junction Connector
No. 2 Cross Member
Combination Meter<14–2>
C2 Condenser Fan Motor and Resistor
C9 Condenser Fan Fuse
20A
FAN NO. 1 Relay
FAN NO. 2 Relay
COMP Relay <16–4>
J14 Junction Connector
D1 Diode (A/C)
J16 Junction Connector
P1 Pressure SW
Single
Right Kick Panel (LHD)
Left Kick Panel (RHD)
10A A/C
Short Pin No. 2
IG1–2 Relay
J13 Junction Connector
I6 Ignition SW
ACC
IG1
ST1
AM1
30A AM1
Short Pin No. 1
60A MAIN2
80A ALT
FL MAIN 3. 0W
Battery
30A E FAN
60A MAIN3