
15096–01

INSPECTION



1. INSPECT CENTER EXHAUST PIPE ASSY

(a) Inspect the pipe assy for rust holes and dents caused by flying stones.

HINT:

- Be particulaly careful in the inspection.
- If there are holes or cracks in the exhaust muffler and pipe, the exhaust noise will increase and may exceed the noise regulation value. In addition, hot gas may blow out, resulting in fire.
- If the exhaust muffler and pipe are severely dented by flying stones, etc., the exhaust resistance will increase. It causes the output of the exhaust gas to decrease and also the fuel consumption to increase.